


**Fresa angular para rasgos, corte à direita (fixação no eixo).**  
 Single angle milling cutter, right hand cut.



**1312**



$\sigma$	d1 js 16 mm	b mm	d2 H7 mm	Z
+ 1°				
60°				
65°				
70°	63	18	22	18
75°				
80°				
85°				

$\sigma$	d1 js 16 pol	b pol	d2 H7 pol	Z
+ 1°				
60°				
65°	2 1/2	1/2	7/8	18
70°				
75°	2 3/4	1/2	1	18
80°				
85°	3	1/2	1	18

